

FMC Pocatello Undocumented Subsurface Conditions

Date/Time (MST) Event Discovered	Event ID	Date/Time (MST) Event area released	Event Quantity in CY (not including sand)	Event Details
10/01/14 (09:30)	USC-1	10/03/14 (08:30)	1.000	09:30 (MST) USC-1, occurred at NW Corner of RA-F in vicinity of Crusher Pad. KW responded and chased area until limits of USC where identified, KW collected approximately 1 CY (not including cover sand) of material and staged it in the vicinity of USC covered it with sand and monitored. USC has been relocated to Coke Settling Basin-2.
10/03/14 (12:00)	USC-2	10/09/14 (17:30)	0.750	12:00 (MST) USC-2 occurred at NE corner of RA-F (adjacent to access road that runs between RA-F and Calciner Ponds). KW responded and chased limits and collected approximately 0.75 CY of material and is stabilized in area of USC. USC has been relocated to Coke Settling Basin-2.
10/6/14 (11:10)	USC-3	10/09/14 (17:30)	0.007	11:10 (MST) USC-3 occurred, material was loaded in off road end dump at RA-F and truck deposited load into RA-C where it was to be graded in as fill. It was when it was deposited into RA-C that USC was made. KW was notified and coned off area.. USC has been relocated to Coke Settling Basin-2.
10/6/14 (11:52)	USC-4	10/09/14 (17:30)	0.500	11:52 (MST) USC-4 occurred at SW Corner of RA-F (on top of slag pile). KW was notified and responded to the scene. This event did not burn out on its own, KW put it out with sand at 12:15 MST. Area of event is coned off. USC has been relocated to Coke Settling Basin-2.
10/7/14 (10:46)	USC-5	10/09/14 (17:30)	0.000	10:46 (MST) USC-5 occurred, material was loaded in off road end dump at RA-F and truck deposited load into RA-C just east of where USC-3 was deposited on 10/6/14. . It was when it was deposited into RA-C that USC was made. I was in area when this occurred, USC burned itself out in 1 minute.KW was notified and has arrived on the scene. USC has been relocated to Coke Settling Basin-2.
10/7/14 (12:04)	USC-6	10/09/14 (17:30)	0.500	At 12:04 (MST) USC-6 occurred, material was loaded in off road end dump at RA-F and truck deposited load into RA-C, SE of where USC-5 was deposited today. It was when it was deposited into RA-C that USC was made. USC has been relocated to Coke Settling Basin-2.
10/7/14 (15:10)	USC-7	10/09/14 (17:30)	0.250	15:10 (MST) USC-7 occurred at SW Corner of RA-F (on top of slag pile, 40' south of USC-4). KW has responded to the scene and placed sand on USC to put out. USC has been relocated to Coke Settling Basin-2.
10/8/2014 (14:23)	USC-8	10/09/14 (17:30)	0.250	14:23 (MST) USC-8 occurred, material was loaded in off road end dump at RA-F and truck deposited load into RA-C just west of where USC-3 was deposited on 10/6/14. It was when it was deposited into RA-C that USC was made. The USC (a 2' x 2' carbon hearth block) stopped smoking by the time KW arrived on the scene. KW consolidated USC-8 with USC-5 and released area back to CB&I. USC has been relocated to Coke Settling Basin-2.
10/8/14 (18:25)	USC-9	10/09/14 (17:30)	0.007	18:25 (MST) USC-9 occurred. USC-9 is located in RA-F (East side top of pile SW of where USC-2 occurred). USC-9 Stopped smoking by the time KW arrived on the scene USC has been relocated to Coke Settling Basin-2.
10/9/14 (10:04)	USC-10	10/09/14 (17:30)	0.250	10:04 (MST) USC-10 occurred. USC-10 is located in RA-F (West side top of slope). KW responded to the scene and relocated material to Coke Settling Basin-2.
10/9/14 (10:27)	USC-11	10/09/14 (17:30)	2.000	10:27 (MST) USC-11 occurred. USC-11 is located in the valley of RA-F. KW responded to the scene and relocated material to Coke Settling Basin-2.
10/9/14 (11:01)	USC-12	10/09/14 (17:30)	0.250	11:01 (MST) USC-12 occurred. USC-12 is located in the valley of RA-F (at entrance on South end). KW responded to the scene and relocated material to Coke Settling Basin-2.

10/9/14 (11:55)	USC-13	10/18/14 (16:10)	0.250	11:55 (MST) USC-13 occurred. USC-13 is located in RA-F (Top of slag pile, West Side in an area that requires 23' cut to meet grade) . USC-13 is what KW is referring to as a "Tiger Pit Material" and is the source of USC-11 and USC-12. KW will delineate area. CB&I has relocated load out operations 50' south of USC-13.
10/10/14 (10:45)	USC-14	10/11/14 (12:00)	1.000	10:45 (MST) USC-14 occurred. USC-14 is located RA-G-South-1-Spent Carbon Rod Pile. KW responded to the scene and relocated material to Coke Settling Basin-2.
10/14/14 (15:25)	USC-15	10/14/14 (16:20)	0.007	15:25 (MST) USC-15 occurred. USC-15 is located RA-H-East. KW delineated the scene and identified (1) "briquette" of material and released area back to CB&I control @ 16:20 on 10/14/14.
10/17/14 (16:04)	USC-16	10/17/14 (17:00)	0.007	At 16:04 (MST), USC-16 occurred. USC-16 is located RA-F West (East slope of valley on North end). KW has been notified and is responding to the scene.
10/20/14 (14:50)	USC-17	10/21/14 (10:00)	0.007	14:50 (MST), USC-17 occurred. USC-17 is located RA-F West (East slope of valley on North end) and consists of (3) smokers in a 20' area approximately 30' up from toe of slope. KW is currently responding to the scene.
10/20/14 (16:30)	USC-18	10/21/14 (15:00)	1.000	KW has identified and area on top slope RA-F West (east side slope north end), which could be possibly be the source for USC-17 and USC-16. KW is delineating area and for tracking purposes this area will be identified as USC-18 (instead of continuation of the other events).
10/22/14 (11:00)	USC-19	10/22/14 (11:31)	0.007	11:00 (MST),USC-19 occurred (event was quick and out in seconds). USC-19 is located RA-F West-top of slag pile (event was quick and out in seconds). KW responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-19, Cliff was onsite giving a tour with Tribal Environmental and Air Quality Reps at the time.
10/22/14 (11:50)	USC-20	10/22/14 (14:30)	0.007	11:50 (MST), USC-20 occurred (this event was quick one also). USC-20 is located RA-F West-top of slag pile, approximately 10' North of USC-19 (event was quick and out in seconds). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-20, Cliff Merrill and Tribal Environmental and Air Quality Reps were still onsite when this event occurred.
10/23/14 (11:05)	USC-21	10/23/14 (14:15)	0.500	11:05 (MST), USC-21 occurred. USC-21 is located RA-G South 1. KW is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-21 by phone.
10/24/14 (13:25)	USC-22	10/24/14 (17:30)	0.750	13:25 (MST), USC-22 occurred in RA-C , material being placed in RA-C is coming out of RA-F. KW is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-22 by phone.
10/24/14 (14:00)	USC-23	10/25/14 (10:20)	0.300	14:00 (MST),USC-23 occurred in RA-F West (Top of Slag Pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-23 by phone.
10/24/14 (15:15)	USC-24	10/24/14 (16:15)	1.000	15:15 (MST), USC-24 occurred in RA-F West (Top of Slag Pile). KW responded to the scene and delineated the area. Cliff Merrill (onsite EPA Rep) was notified of USC-24 by phone.
10/25/14 (16:10)	USC-25	10/25/14 (16:10)	0.250	14:45 (MST), on 10/25/14, USC-25 occurred in RA-F West (Top of Slag Pile). KW has responded to the scene and delineated the area. Cliff Merrill (onsite EPA Rep) was notified of USC-25 by phone.
10/27/14 (09:10)	USC-26	10/27/14 (09:40)	0.250	09:10 (MST), USC-26 occurred in RA-F (North end of the valley). KW has responded to the scene and delineated the area. Cliff Merrill (onsite EPA Rep) was onsite when this occurred and was notified of USC-26.
10/27/14 (13:42)	USC-27	10/27/14 (16:15)	0.037	13:42 (MST), USC-27 occurred (2) smokers in RA-F, (North end of valley). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-27 by phone.
10/27/14 (14:45)	USC-28	10/28/14 (12:15)	1.500	14:45 (MST), USC-28 occurred in RA-F West, (Top of slag pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-28 by phone.
10/27/14 (15:20)	USC-29	10/28/14 (13:30)	0.037	15:20 (MST), USC-29 occurred in RA-F West, (Top of slag pile-North end). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-29 by phone.
10/27/14 (15:49)	USC-30	10/27/14 (17:35)	0.037	15:49 (MST), USC-30 occurred in RA-F West, (Top of slag pile-North end) approximately 20' North of USC-29. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-30 by phone.
10/27/14 (16:50)	USC-31	10/27/14 (17:50)	0.055	16:50 (MST), USC-31 occurred in RA-F West, (North end of the valley). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-31 by phone.

10/27/14 (16:51)	USC-32	10/27/14 (18:00)	0.037	16:51 (MST), USC-32 occurred in RA-F West, (South end of the valley). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-32 by phone.
10/28/14 (14:10)	USC-33	10/28/14 (18:10)	0.019	14:10 (MST),USC-33 occurred in RA-F West, (top of slag pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-33 by phone.
10/28/14 (17:00)	USC-34	10/28/14 (17:25)	0.007	17:00 (MST), USC-34 occurred in RA-C. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-34 by phone.
10/28/14 (17:50)	USC-35	10/28/14 (18:10)	0.007	17:50 (MST), USC-35 occurred in RA-C. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-35 by phone.
10/30/14 (13:40)	USC-36	10/30/14 (15:00)	0.037	13:40 (MST),USC-36 occurred in RA-G South 1. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-36 by phone.
10/30/14 (14:10)	USC-37	10/30/14 (15:20)	0.007	14:10 (MST), USC-37 occurred in RA-G South 1 (approximately 75' SE of USC-36). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-37.
10/30/14 (15:25)	USC-38	10/30/14 (16:00)	0.007	15:25 (MST), USC-38 occurred in RA-F West (top of slag pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-38
10/31/14 (08:25)	USC-39	11/01/14 (11:57)	4.000	08:25 (MST) USC-39 occurred in RA-F West (top of slag pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-39. KW will continue with delineation on 11/1/14. KW removed approximately 11.9 CY (including stabilization sand)of material from this area.
10/31/14 (09:28)	USC-40	10/31/14 (14:50)	0.004	09:28 (MST),USC-40 occurred in RA-F West (top of slag pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-40.
10/31/14 (13:50)	USC-41	11/01/14 (08:45)	0.500	13:50 (MST), USC-41 occurred in RA-G South 1. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-41. KW will continue with delineation on 11/1/14.
11/01/14 (12:44)	USC-42	11/01/14 (17:57)	0.500	12:44 (MST),USC-42 occurred in RA-F (top of slag pile, consisting of 3 smokers). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-42.
11/01/14 (15:15)	USC-43	11/01/14 (15:40)	0.007	15:15 (MST),USC-43 occurred in RA-F-Valley. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-43.
11/03/14 (08:12)	USC-44	11/03/14 (08:45)	0.004	08:12 (MST), on 11/03/14, USC-44 occurred in RA-F-Valley (South end). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-44.
11/03/14 (14:20)	USC-45	11/03/14 (14:45)	0.037	14:20 (MST), USC-45 occurred in RA-F-Valley (mid valley). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-45.
11/03/14 (15:45)	USC-46	11/04/14 (08:30)	0.007	15:45 (MST), USC-46 occurred in RA-F-Valley (North end). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-46. KW did not find any USC material after delineating area.
11/04/14 (13:45)	USC-47	11/04/14 (14:15)	0.000	13:45 (MST), USC-47 occurred in RA-F-Valley (mid-valley). KW has been notified and is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-47. KW unable to find source of USC event after delineating area.
11/04/14 (13:45)	USC-48	11/04/14 (14:15)	0.007	13:46 (MST), USC-48 occurred in RA-F-West (top of pile). KW has been notified and is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-48.
11/04/14 (16:25)	USC-49	11/04/14 (16:45)	0.007	16:25 (MST), USC-49 occurred in RA-F-Valley (North End). KW has been notified and is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-49.
11/05/14 (10:50)	USC-50	11/05/14 (13:30)	0.055	10:50 (MST), USC-50 occurred in RA-B, material being placed in RA-B is coming from RA-F West (top of pile). KW has responded to RA-B and investigated source area in RA-F. KW released areas at 13:25.Cliff Merrill (onsite EPA Rep) was notified of USC 50.
11/05/14 (15:50)	USC-51	11/05/14 (16:05)	0.000	15:50 (MST), USC-51 occurred in RA-F West (top of pile). KW is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC 51. KW unable to find source of USC event after delineating area.
11/05/14 (16:35)	USC-52	11/06/14 (09:05)	1.000	16:35 (MST), USC-52 occurred in RA-F West (top of pile). KW has responded to the scene and stabilized the area, KW will delineate on 11/6/14. Cliff Merrill (onsite EPA Rep) was notified of USC 52.

11/06/14 (10:40)	USC-53	11/06/14 (16:45)	12.000	10:40 (MST), USC-53 occurred in RA-F Valley. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC 53.
11/06/14 (10:42)	USC-54	11/21/14 (17:00)	84.000	10:42 (MST), USC-54 occurred in RA-F West (top of pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC 54. KW worked on delineating area through out the day on 11/7/14 and did not complete, KW will resume delineation on 11/8/14. Delineation of USC-54 was not completed on 11/8/14, to date approximately 30-35 CY of material was removed from event area, KW will resume with delineation on 11/10/14.
11/06/14 (11:40)	USC-55	11/06/14 (13:10)	0.037	11:40 (MST), USC-55 occurred in RA-C (material came out of an End Dump which was loaded in RA-F). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC 55.
11/07/14 (10:50)	USC-56	11/07/14 (11:30)	0.007	10:50 (MST),USC-56 occurred in RA-F West -South side on access ramp. The event when called in was reported as (1) smoker, when KW arrived on scene smoker was out. Cliff Merrill (onsite EPA Rep) was notified of USC 56.
11/08/14 (13:09)	USC-57	11/08/14 (13:40)	0.007	13:09 (MST), on 11/8/14, USC-57 occurred in RA-F Valley-North end. KW responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC 57. Tim Whiteus informed the CM that he collected (2) nuggets slightly larger than a softball each from this event.
11/10/14 (08:48)	USC-58	12/10/14 (12:00)	105.000	08:48 (MST), USC-58 occurred in RA-F East (top of slag pile). KW responded to the scene and stabilized the area. Cliff Merrill (onsite EPA Rep) was notified of USC 58. Tim Whiteus stated that on initial assessment of area USC-58 is a larger area than USC-54 which is still being delineated. Delineation of this event was completed on 12/10/14.
11/11/14 (10:29)	USC-59	11/11/14 (11:30)	0.007	10:29 (MST), USC-59 occurred in RA-F Valley (North end). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC 59.
11/11/14 (14:59)	USC-60	11/11/14 (16:15)	0.000	14:59 (MST), USC-60 occurred in RA-F Valley (North end, material came from top of RA-F East). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-60. KW unable to find source of USC event after delineating area.
11/13/14 (16:00)	USC-61	11/14/14 (08:30)	0.037	16:00 (MST), USC-61 occurred in RA-F West (top of slag pile) KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-61.
11/18/14 (16:00)	USC-62	11/19/14 (11:40)	0.500	16:00 (MST), USC-62 occurred in RA-F West (top of slag pile, North end) KW has responded to the scene and stabilized the area. Cliff Merrill (onsite EPA Rep) was notified of USC-62. KW will delineate USC-62 on 11/19/14.
11/18/14 (16:34)	USC-63	11/20/14 (16:00)	10.000	16:34 (MST), USC-63 occurred in RA-F West, top of slag pile, North end approximately 50 yards SW of USC-62. KW has responded to the scene and stabilized the area. Cliff Merrill (onsite EPA Rep) was notified of USC-63. KW will delineate USC-63 on 11/19/14.
11/19/14 (08:19)	USC-64	11/19/14 (11:40)	0.500	08:19 (MST), USC-64 occurred in RA-F West, top of slag pile, North end. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-64.
11/19/14 (15:02)	USC-65	11/19/14 (15:25)	0.007	15:02 (MST), USC-65 occurred in RA-F West, top of slag pile, North end. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-65.
11/19/14 (16:05)	USC-66	11/19/14 (16:40)	0.007	16:05 (MST),USC-66 occurred in RA-F West, top of slag pile, North end. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-66.
11/20/14 (07:45)	USC-67	11/20/14 (10:30)	0.037	07:45 (MST), USC-67 occurred in RA-F West, top of slag pile, just north of USC-63, North end. KW was notified and responded to the scene and stabilized. Cliff Merrill (onsite EPA Rep) was notified of USC-67.
11/21/14 (13:52)	USC-68	11/21/14 (14:20)	0.007	13:52(MST), USC-68 occurred in RA-F Valley (north end) KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-68.
11/22/14 (08:21)	USC-69	11/22/14 (08:50)	0.037	08:21 (MST), USC-69 occurred in RA-F Valley (north end) KW has responded to the scene and stabilized. Cliff Merrill (onsite EPA Rep) was notified of USC-69.

11/22/14 (11:50)	USC-70	11/22/14 (12:10)	0.037	11:50 (MST), USC-70 occurred in RA-F Valley (north end) KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-70.
11/22/14 (15:35)	USC-71	11/26/14 (08:30)	18.000	15:35 (MST), USC-71 occurred in RA-F West ,top of slag pile, in vicinity of where USC-54 was located. KW is responding to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-71. KW released USC-71 On 11/26/14.
11/25/14 (16:20)	USC-72	11/25/14 (16:40)	0.019	16:20 (MST), USC-72 occurred in RA-F West ,top of slag pile NW corner. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-72.
11/26/14 (10:29)	USC-73	11/26/14 (12:00)	0.037	10:29 (MST), USC-73 occurred in RA-F West ,top of slag pile. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-73.
12/01/14 (10:29)	USC-74	12/01/14 (17:00)	0.111	14:30 (MST), USC-74 occurred in RA-F (west side of the valley approximately 10' from toe of slope), dozer was pushing material from the top of RA-F West . KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-74.
12/02/14 (08:00)	USC-75	12/02/14 (08:30)	0.007	08:00 (MST), USC-75 occurred in RA-F (west side of the valley approximately 100' south of north end and 20' from toe of slope), dozer was pushing material from the top of RA-F West . KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-75.
12/02/14 (13:20)	USC-76	12/02/14 (16:50)	0.007	13:20 (MST), USC-76 occurred in RA-F West (top of slag pile) . KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-76.
12/04/14 (14:54)	USC-77	12/04/14 (15:30)	0.007	14:54(MST), USC-77 occurred in RA-F West (top of slag pile) . KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-77.
12/09/14 (15:20)	USC-78	12/10/14 (08:30)	0.007	15:20 (MST), USC-78 Occurred in RA-F West. KW has responded and removed a 4"x4"x3" piece. KW will delineate and search for more material. Cliff Merrill (onsite EPA Rep) was notified of USC-78.
12/10/14 (10:19)	USC-79	12/15/14 (15:45)	170.000	10:19 (MST), on 12/10/14, USC-79 occurred in RA-F West (top of slag pile, top of west slope in vicinity of where USC-78 occurred). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-79.
12/12/14 (08:20)	USC-80	12/12/14 (08:35)	0.007	08:20 (MST),USC-80 occurred in RA-F East (top of slag pile, in the area where USC-58 occurred). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-80.
12/12/14 (08:55)	USC-81	12/12/14 (09:00)	0.007	08:55 (MST),USC-81 occurred in RA-F West Slope of Valley (material dozer pushed from top of RA-F). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-81.
12/12/14 (09:03)	USC-82	12/12/14 (09:20)	0.007	09:03 (MST), USC-82 occurred in RA-F Valley North end. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-82.
12/12/14 (11:20)	USC-83	12/12/14 (11:30)	0.000	11:20 (MST), USC-83 occurred in RA-B (material being placed is from top of slag pile RA-F East). KW has responded to the scene Cliff Merrill (onsite EPA Rep) was notified of USC-83. KW reported that they could not locate any material to recover from this event.
12/12/14 (13:40)	USC-84	12/12/14 (14:15)	0.007	13:40 (MST), USC-84 occurred in RA-F East (top of slag pile in vicinity of USC-80). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-84.
12/13/14 (08:19)	USC-85	12/13/14 (10:30)	0.045	08:19 (MST), USC-85 occurred in RA-B (material that is being placed is coming from RA-F East top of slag pile). KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-85.
12/13/14 (11:34)	USC-86	12/13/14 (12:00)	0.007	11:34 (MST), USC-86 occurred in RA-F East, top of slag pile in NW corner where dozers are pushing. KW has responded to the scene. Cliff Merrill (onsite EPA Rep) was notified of USC-86.
12/19/14 (07:30)	USC-87	12/19/14 (16:00)	0.000	07:30 (MST), USC-87 -RA-C requires a cut to meet grade, within the cut is an abandoned Phossy Water Line. KW was on scene throughout the day to respond to and investigate any other pipe exposed during grading operations. Cliff Merrill (onsite EPA Rep) was notified of USC-87. CB&I exposed Phossy water line intact. The grading plan for this area of RA-C was modified (as submitted to EPA January 21, 2015) to eliminate cut and the exposed line will be re-covered with fill.

3/11/15 (12:00)	USC-88	3/13/15 (15:00)	0.007	12:00 (MST), USC-88 occurred in RA-F, (North end in the area where CB&I is expanding crusher pad). KW has responded to the scene and stabilized. No EPA rep available to notify on this event.
3/12/15 (14:58)	USC-89	3/13/15 (15:30)	100.000	14:58 (MST), USC-89 occurred in RA-F West , top of slag pile mid-way, top of west slope. KW has responded to the scene and stabilized.
3/16/15 (15:10)	USC-90	3/16/15 (15:30)	0.007	15:10 (MST), USC-90 occurred in RA-F-North end in haul road between RA-F East and RA-F West,(South of crusher pad area). KW has responded to the scene and stabilized. Cliff Merrill EPA rep was notified.
3/17/15 (09:43)	USC-91	3/20/15 (11:30)	65.100	09:43 (MST), USC-91 occurred in RA-F western slope. KW has responded to the scene and stabilized. Cliff Merrill EPA rep was notified.
3/17/15 (10:27)	USC-92	3/17/15 (10:50)	0.007	10:27 (MST), USC-92 occurred in RA-B/C fill area. KW has responded to the scene. Cliff Merrill EPA rep was notified.
3/17/15 (11:07)	USC-93	3/21/15 (17:45)	0.207	11:07 (MST), USC-93 occurred in RA-B/C fill area. KW has responded to the scene. Cliff Merrill EPA rep was notified.
3/18/15 (09:55)	USC-94	3/18/15 (10:40)	0.007	09:55 (MST), USC-94 occurred in RA G-North. KW has responded to the scene. Cliff Merrill EPA rep was notified.
3/20/15 (12:10)	USC-95	5/9/15 (17:00)	36.800	12:10 (MST), USC-95 occurred in RA C near power lattice tower in NW corner. KW was notified and responded to the scene and began delineation . Cliff Merrill EPA rep was notified. Area was closed on 5/9/15.
3/23/15 (14:56)	USC-96	3/28/15 (17:45)	5.090	14:56 (MST), USC-96 occurred in RA B. KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
3/23/15 (15:05)	USC-97	3/23/15 (17:00)	0.074	15:05 (MST),USC-97 occurred in RA C (approx 100 yards east of USC-95) . KW has responded to the scene. Cliff Merrill EPA rep was notified.
3/23/15 (15:36)	USC-98	3/28/15 (17:45)	3.620	15:36 (MST), USC-98 occurred in RA C (east side) . KW has responded to the scene. Cliff Merrill EPA rep was notified.
3/30/15 (09:15)	USC-99	3/30/15 (09:40)	0.001	09:15 (MST), USC-99 occurred in RA G North . KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
3/30/15 (10:15)	USC-100	3/30/15 (10:40)	0.001	10:18 (MST), USC-100 occurred in RA-F (Crusher Pad Area) . KW was notified and has responded to the scene. Cliff Merrill EPA rep was notified.
3/31/15 (16:56)	USC-101	3/31/15 (17:30)	0.003	16:56 (MST), USC-101 occurred in RA-North (South Side) . KW was notified and has responded to the scene. Cliff Merrill EPA rep was notified.
4/1/15 (11:45)	USC-102	4/1/15 (16:15)	2.500	11:45 (MST), 04/01/15, USC-102 occurred in RA-F West-top of west slope . KW was notified and has responded to the scene. Cliff Merrill EPA rep was notified.
4/6/15 (09:40)	USC-103	4/6/15 (09:55)	0.003	09:40 (MST), USC-103 occurred in RA-G North. KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
4/6/15 (12:04)	USC-104	4/6/15 (14:40)	1.500	12:04 (MST),USC-104 occurred in RA-F East (North end; toe of East slope). KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
4/6/15 (13:34)	USC-105	4/6/15 (14:45)	0.003	13:34 (MST), USC-105 occurred in RA-B. KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
4/6/15 (14:30)	USC-106	4/6/15 (15:15)	0.003	14:30 (MST), USC-106 occurred in RA-B (East end). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
4/7/15 (08:55)	USC-107	4/7/15 (16:40)	0.003	08:55 USC-107 occurred in RA-B (west end). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/8/15 (08:10)	USC-108	4/8/15 (10:30)	1.750	08:10 (MST), USC-108 occurred in RA-B (center of pad). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/8/15 (11:48)	USC-109	4/8/15 (17:30)	14.000	11:48 (MST), USC-109 occurred in RA-F East (toe of east slope). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.

4/8/15 (12:15)	USC-110	4/8/15 (13:15)	0.007	12:15 (MST), USC-110 occurred in RA-G North (east end). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/9/15 (07:50)	USC-111	4/9/15 (17:30)	0.007	07:50 (MST), USC-111 occurred in RA-B. KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
4/9/15 (10:15)	USC-112	4/9/15 (14:00)	7.500	10:15 (MST), USC-112 occurred in RA-F East (toe of east slope). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
4/10/15 (07:45)	USC-113	4/10/15 (09:30)	0.000	07:55 (MST), USC-113 was opened in RA-F East (toe of east slope) to explore area. KW delineated area and found no material. Darlene McCray EPA rep was notified.
4/10/15 (13:50)	USC-114	4/10/15 (14:55)	0.037	13:50 (MST), USC-114 occurred in RA-F West (top of pile north end, near haul road). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/11/15 (12:16)	USC-115	4/11/15 (17:30)	0.007	12:16 (MST), USC-115 occurred in RA-B. KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/11/15 (14:00)	USC-116	4/11/15 (17:30)	0.007	14:00 (MST), USC-116 occurred in RA-E North. KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/11/15 (16:45)	USC-117	4/11/15 (17:30)	0.037	16:45 (MST), USC-117 occurred in RA-F (south end of the valley). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/13/15 (15:10)	USC-118	4/13/15 (16:15)	0.000	15:10 (MST), USC-118 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified. KW reported that they could not locate any material to recover from this event.
4/13/15 (16:15)	USC-119	4/13/15 (17:15)	0.007	16:15 (MST), USC-119 occurred in RA-F East (toe of slope, backside). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
4/14/15 (10:12)	USC-120	4/14/15 (17:15)	0.007	10:12 (MST), USC-120 occurred in RA-G North (east end). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/15/15 (13:30)	USC-121	4/15/15 (14:30)	0.007	13:30 (MST), USC-121 occurred in RA-B. KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
4/16/15 (13:30)	USC-122	4/16/15 (13:30)	0.002	09:14 (MST), USC-122 occurred at crushing operation in RA-F. KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/16/15 (13:30)	USC-123	4/16/15 (13:30)	0.000	11:00 (MST), USC-123 occurred in RA-D East, (RA-F material being placed in RA-D East). KW was notified and responded to the scene.. Darlene McCray EPA rep was notified.
4/17/15 (17:00)	USC-124	4/17/15 (17:30)	0.007	17:00 (MST), USC-124 occurred in RA-C. KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/18/15 (11:20)	USC-125	4/18/15 (12:00)	0.000	11:20 (MST), USC-125 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Darlene McCray EPA rep was notified. KW reported that they could not locate any material to recover from this event.
4/24/15 (08:37)	USC-126	4/24/15 (09:00)	0.000	08:37 (MST), USC-126 occurred in RA-B (material being placed came from RA-F East). KW was notified and responded to the scene. Darlene McCray EPA rep was notified. KW reported that they could not locate any material to recover from this event.
4/24/15 (15:03)	USC-127	4/24/15 (16:00)	0.074	15:03 (MST), USC-127 occurred in RA-B (material being placed came from RA-F East). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/25/15 (14:03)	USC-128	4/25/15 (15:00)	0.001	14:03 (MST), USC-128 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/29/15 (11:32)	USC-129	4/29/15 (11:32)	0.001	11:32 (MST), USC-129 occurred in RA-F East (south side toe of slope). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
4/30/15 (08:42)	USC-130	4/30/15 (09:45)	0.001	08:42 (MST), USC-130 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.

5/2/15 (07:56)	USC-131	5/2/15 (17:30)	0.002	07:56 (MST), USC-131 occurred in RA-G North (East end). KW was notified and responded to the scene. Darlene McCray EPA rep was notified.
5/5/15 (08:15)	USC-132	5/5/15 (08:45)	0.002	08:15 (MST), USC-132 occurred in RA-F Valley (south end). KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
5/6/15 (13:41)	USC-133	5/6/15 (15:15)	0.001	13:41 (MST), USC-133 occurred in RA-F West (North end, feed side of the crusher). KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
5/7/15 (13:30)	USC-134	5/7/15 (14:00)	0.002	13:30 (MST), USC-134 occurred in RA-F West-Crushing Operations. KW has been notified and is responding to the scene. Cliff Merrill EPA rep was notified.
5/8/15 (09:35)	USC-135	5/8/15 (12:00)	0.000	09:35 (MST), USC-135 occurred in RA-G North-East end. KW was notified and responded to the scene.. Cliff Merrill EPA rep was notified. KW reported that they could not locate any material to recover from this event.
5/8/15 (13:20)	USC-136	5/8/15 (17:00)	1.000	13:20 (MST), USC-136 occurred in RA-E North. KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
5/8/15 (15:40)	USC-137	5/8/15 (16:20)	0.005	15:40 (MST), USC-137 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
5/11/15 (09:27)	USC-138	5/11/15 (11:00)	0.500	09:27 (MST), USC-138 occurred in RA-F East (top of slag pile-NE Corner). KW was notified and responded to the scene. . Cliff Merrill EPA rep was notified.
5/13/15 (07:58)	USC-139	5/13/15 (17:30)	0.500	07:58 (MST), USC-139 occurred in RA-E North-East end. KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
5/13/15 (13:22)	USC-140	5/13/15 (14:00)	0.001	13:22 (MST), USC-140 occurred in RA-D East. KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
5/14/15 (11:45)	USC-141	5/14/15 (16:56)	0.000	11:45 (MST), USC-141 occurred in RA-F West (feed end of the crusher). KW was notified and responded to the scene. Tim Norman EPA rep was notified. KW reported that they could not locate any material to recover from this event.
5/14/15 (16:08)	USC-142	5/14/15 (16:56)	0.002	16:08 (MST), USC-142 occurred in RA-F East (NE corner). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
5/15/15 (16:07)	USC-143	5/15/15 (17:00)	0.003	16:07 (MST), USC-143 occurred in RA-C. KW was notified and responded to the scene. Tim Norman EPA rep was notified.
5/16/15 (11:10)	USC-144	5/16/15 (12:10)	0.000	11:10 (MST), USC-144 occurred in RA-F West-NW Slope. KW was notified and responded to the scene. Tim Norman EPA rep was notified. KW reported that they could not locate any material to recover from this event.
5/18/15 (16:15)	USC-145	5/18/15 (16:50)	0.007	16:15 (MST), USC-145 occurred in RA-C (West end). KW was notified and responded to the scene.. Tim Norman EPA rep was notified.
5/19/15 (12:19)	USC-146	5/19/15 (17:00)	0.035	12:19 (MST), USC-146 occurred in RA-C (West end-South of lattice tower). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
5/20/15 (15:13)	USC-147	5/20/15 (16:30)	0.134	15:13 (MST), USC-147 occurred in RA-F East (NE corner top of pile). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
5/21/15 (07:38)	USC-148	5/21/15 (17:30)	1.500	07:38 (MST), USC-148 occurred in RA-F East (NE corner top of pile). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
5/28/15 (15:35)	USC-149	5/28/15 (17:30)	0.074	15:35 (MST), USC-149 occurred in RA-F East (top of slag West side). KW was notified and responded to the scene.. Cliff Merrill EPA rep was notified.
5/30/15 (09:48)	USC-150	5/30/15 (10:50)	0.050	09:48 (MST), USC-150 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
5/30/15 (11:10)	USC-151	5/30/15 (16:50)	0.074	11:10 (MST), USC-151 occurred in RA-C (West end near lattice tower). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.

5/30/15 (14:58)	USC-152	Stabilized/Not Delineated	0.025	14:58 (MST), USC-152 occurred in RA-C (SW corner). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified. Stabilized/Not Delineated, CY of material recovered to date.
6/02/15 (08:21)	USC-153	6/02/15 (18:00)	0.001	08:21 (MST), USC-153 occurred in RA-F East (East side). KW was notified and responded to the scene. Cliff Merrill EPA rep was notified.
6/05/15 (14:00)	USC-154	6/05/15 (17:15)	0.001	14:00 (MST), USC-154 occurred in RA-F East (top of slag pile in the middle). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
6/06/15 (09:33)	USC-155	6/06/15 (17:30)	1.000	09:33 (MST), USC-155 occurred in RA-F West (North end-South of Crushing Plant). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
6/08/15 (15:15)	USC-156	6/08/15 (17:00)	0.000	15:15 (MST), USC-156 occurred in RA-C. KW has been notified and is responding to the scene. Tim Norman EPA rep was notified. KW reported that they could not locate any material to recover from this event.
6/09/15 (07:30)	USC-157	6/09/15 (17:00)	0.001	07:30 (MST), USC-157 occurred in RA-F East (top of slag pile). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
6/09/15 (14:58)	USC-158	6/09/15 (17:00)	0.003	14:58 (MST), USC-158 occurred in RA-F West (South of crushing operation). KW was notified and responded to the scene. Tim Norman EPA rep was notified.
		Total CY not including stabilization sand=	662.83	